



# FACILITY COMPLIANCE INSPECTION REPORT

## Division of Waste Management Solid Waste Section

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS		<b>COUNTY:</b> Bladen <b>PERMIT NO.:</b> 0901-MSWLF-1981 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF	<b>X</b>	HHW		White goods		Incin		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** May 14, 2013

**Date of Last Inspection:** February 22, 2012

**FACILITY NAME AND ADDRESS:**

Bladen County Landfill, 1522 Mercer Mill Road, Elizabethtown, NC 28337

**GPS COORDINATES:** N: 34.60645 E: -78.61160

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Robert Mazur, General Services Manager

Telephone: 910-872-6320

Email address: rmazur@bladencounty.org

Fax: 910-645-2181

**FACILITY CONTACT ADDRESS:**

272 Smith Circle, Elizabethtown, North Carolina 28337

**PARTICIPANTS:**

Drew Hammonds, Solid Waste Section

Steve Melson, Bladen County Solid Waste

**STATUS OF PERMIT:**

Closed

**PURPOSE OF SITE VISIT:**

Comprehensive Audit

**STATUS OF PAST NOTED VIOLATIONS:**

None

**OBSERVED VIOLATIONS**

1.

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. The facility is secured with a gate to prevent unauthorized access.
2. Semi-annual groundwater monitoring documents are on the CARA website.
3. An eroded area was observed on the eastern side of the closed landfill. The eroded area needs to be repaired and vegetative cover established.
4. The vegetation on the majority of the closed landfill was approximately 24 inches in height. County staff will contact me once mowing has been completed for a follow up inspection of the landfill and monitor wells.
5. Digital photos were taken during this audit.

Please contact me if you have any questions or concerns regarding this inspection report.



Drew Hammonds  
Environmental Senior Specialist  
***Regional Representative***

Phone: 910-433-3350

<b>Sent on:</b> May 17, 2013	<input checked="" type="checkbox"/>	Email	<input type="checkbox"/>	Hand delivery	<input type="checkbox"/>	US Mail	<input type="checkbox"/>	Certified No. <input type="checkbox"/>
------------------------------	-------------------------------------	-------	--------------------------	---------------	--------------------------	---------	--------------------------	--

Copies: Dennis Shackelford, Eastern District Supervisor (email)  
Jessica Montie, Compliance Officer (email)  
Robert Mazur, Bladen County General Services Manager (email)  
Steve Melson, Bladen County Solid Waste (email)



Cover on closed MSWLF.



Eroded area on east side of closed MSWLF.